CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

OnlinePortal at DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20246286

Address: 1338 SW WINTHROP TER, LEES SUMMIT, MO 640811336 SW WINTHROP TER, LEES SUMMIT, MO

64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Erosion Control Inspection Dustin Agcopra Failed Thursday, October 02,

Residential 2025

Corrective Action Required:

1 DCM2 ESC DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS
DEFICIENT UNTIL ADEQUATE EROSION CONTROL PROVIDED.
INSTALLATION

- REPAIR DOWNED SILT FENCE AROUND LOT

- MAINTAIN GRAVEL ENTRANCE

Corrective Action Required:

DCM3 ESC 7-17-25 Dustin A, Silt fence is down road and curb line needs to be cleaned.

REQUIRED 2 DAY Concrete washout area needs to be cleaned up and maintained. Storm inlets

need to be cleaned. EROSION CONTROL REQUIRED. EROSION CONTROL

SHALL BE IN COMPLIANCE WITHIN TWO BUSINESS DAYS. 7-21-25 Dustin A, Nothing has been done to correct this.

8-4-25 Dustin A, All corrections had been made, esc must be maintained

throughout project.

Corrective Action Required:

DCM3 ESC 10-2-25 Dustin A, Silt fence is down on lot and streets and curb needs to be REQUIRED 2 DAY cleaned. EROSION CONTROL REQUIRED. EROSION CONTROL SHALL BE IN

Cleaned, ENOSION CONTROL REQUIRED. ENOSION CONTROL SIL

COMPLIANCE WITHIN TWO BUSINESS DAYS.

Comments:

2