

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200

OnlinePortal at DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20234052
Address: 150 NE TUDOR RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Engineering	John Jackson	Passed	Thursday, October 30, 2025

Corrective Action Required:

1	Misc	Failed occupancy contractor has not installed check valve for backflow. This is a requirement before building occupancy is granted. * changed outcome to Failed for no Occupancy ***
---	------	--

Corrective Action Required:

2	Misc	10/30/25 Thursday JMJ Backflow issue was resolved & vegetation for the detention basin is acceptable.
---	------	--

Comments: