

Report Email: thomas@redfordconstruction.
 Copy Email:
 Lab Report Fax No: (816) 540-3071
 Lab Report Contact 1: (816) 540-2030
 Lab Report Contact 2:
 Customer ID No: 8334
 Customer PO No:
 Collected By: Client
 Invoice No: 66664

Mike Bader
 Redford Construction
 PO Box 1065

Raymore, MO 64083

Report of Analysis

Laboratory Report ID No:

21315

Project Name: Whispering Woods

Item No.	Cat NO	ANALYSIS	COLLECTED	ANALYZED	REPORTING LIMIT	RESULTS
	Line NO	SAMPLE TYPE	SAMPLE SITE NOTES		TEST METHOD	
1	6191	Bacteria, P/A E. coli	2/17/26	2/18/26	1 CFU/100mL	Negative CFU/100mL
	143935	Grab	Sample 1		SM9223 B	
2	6191	Bacteria, P/A E. coli	2/17/26	2/18/26	1 CFU/100mL	Negative CFU/100mL
	143936	Grab	Sample 2		SM9223 B	
3	6190	Bacteria, P/A Total coliform	2/17/26	2/18/26	1 CFU/100mL	Negative CFU/100mL
	143934	Grab	Sample 1		SM9223 B	
4	6190	Bacteria, P/A Total coliform	2/17/26	2/18/26	1 CFU/100mL	Negative CFU/100mL
	143937	Grab	Sample 2		SM9223 B	

Comments, if present, concern this Lab Work Order:

The reported analytical results relate only to the sample submitted.

This report shall not be reproduced, except in full, without written approval by Blue Valley Laboratories, Inc.