

City of Lee's Summit

Department of Planning & Development 220 SE Green Street Lee's Summit, Missouri 64063 (816) 969-1600 Fax (816) 969-1619

Final Inspection Report

Inspection Summary

Permit #: PRCOM20112705, Building Permit - Commercial Address: 1201 SW 3RD ST, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Planning	Christina Stanton, Planner	Failed	Thursday, August 09, 2012
Corrective Action Required 1	limestone as was sh If a different mater Planning and must that was approved states: The conver	nown on the approve ial is to be used it v first meet the requ for the Preliminary nience store pump is rside of the canopy	be encased in the thinset ed Final Development Plan. vill need to be reviewed by uirement of the Ordinance Development Plan, which land canopy columns from v shall be brick, masonry,
Corrective Action Required 2	Handicapped Acce parking spaces sha other structure, loo inches above the g at the head of the	ssible Sign and Ais Il be identified by a s cated between third round, measured fro parking space. The	sle Markings. Accessible sign, mounted on a pole or ty-six (36) and sixty (60) om the bottom of the sign, e accessible aisle shall be the Federal Americans with
Corrective Action Required	the approved Final I test the lighting lev	Development Plan. els once all the ligh ED requirements per	Il be installed as shown on The Planning Director shall nting has been installed to taining to lighting for video
Corrective Action Required 4	Landscaping. Insta Final Development		as shown on the approved

Occupancy Inspection -	Christina Stanton, Planner	Failed	Friday, August 24, 2012



City of Lee's Summit

Department of Planning & Development 220 SE Green Street Lee's Summit, Missouri 64063

(816) 969-1600 Fax (816) 969-1619

Planning	
Corrective Action Required	
1	Canopy Columns. The brick encasement of the canopy columns, from grade to the underside of the canopy, shall be completed prior to issuance of TCO.
Corrective Action Required	
2	Handicapped Accessible Sign. The correct sign is noted on details #10 and #17 of Sheet C8.0. Correct prior to Final Occupancy.
Corrective Action Required	
3	Landscaping. The following items shall be addressed before Final Occupancy:
	The trees that are in the utility easement shall be moved just outside of the easement per Public Works.
	Two shrubs shall be added to the screening to the south as was discussed.
	Those areas not otherwise landscaped shall be sodded.
Corrective Action Required	
4	Lighting. The lighting levels shall be verified by the Director of Planning and Development prior to Final Occupancy.

Occupancy Inspection - Planning	Christina Stanton, Planner Temporary C of O Monday, August 27, 2012
Corrective Action Required	
1	Handicapped Accessible Sign. The correct sign is noted on details #10 and #17 of Sheet C8.0. Correct prior to Final Occupancy.
Corrective Action Required	
2	Lighting. The lighting levels shall be verified by the Director of Planning & Development prior to Final Occupancy.

Occupancy Inspection - Planning	Christina Stanton, Planner Temporary C of O Monday, August 27, 2012
Corrective Action Required 1 MISC	Handicapped Accessible Sign. The correct sign is noted on details #10 and #17 of Sheet C8.0. Correct prior to Final Occupancy.
Corrective Action Required 2 MISC	Lighting. The lighting levels shall be verified by the Director of Planning & Development prior to Final Occupancy.



City of Lee's Summit

Department of Planning & Development 220 SE Green Street Lee's Summit, Missouri 64063

(816) 969-1600 Fax (816) 969-1619

Occupancy Inspection - Planning	Christina Stanton, Planner Temporary C of O Friday, November 02, 2012
Corrective Action Required 1	Handicapped Accessible Sign. The correct sign is noted on details #10 and #17 of Sheet C8.0. Correct prior to Final Occupancy.
Corrective Action Required 2	Landscaping. Three evergreens and two deciduous trees have died and need to be replaced.
Corrective Action Required 3 Corrective Action Required	Directional Sign. The directional sign located beneath the stop sign shall be removed. A permit must be obtained prior to posting signage. If the applicant would like to keep said sign they need to indicate so, dimensions, proposed location and height for review by Planning Commission with additional signage.
4	Electrical Permit. There is a shed which appears to have electrical service going to it, but staff does not see any indication that an electrical permit or inspection was ever completed. Please contact Codes Inspector and correct this matter.

Comments: