

CITY OF LEE'S SUMMIT CODES ADMINISTRATION 220 SE GREEN ST. P.O.BOX 1600

PHONE: 816-969-1200

FAX: 816-969-1201

## Inspection Summary

Permit #: PRCOM20121405, Building Permit - Commercial Address: 178 NW OLDHAM PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Above Ceiling Inspection	John Borns	Partial	Thursday, November 08, 2012
Partial Correction 1 MISC	ABC	VE-CEILING SYSTEMS	ADY GWB CEILING/SOFFIT FRAMING + S @ FOLLOWING SPACES: TWO + M/W SHOWERS; 131; 150 151; 161;
Partial Correction 2 MISC	BUL		ADY FRAMING OF HANGING 5/D.8; AT EAST WALL OF SPACES 122,
Partial Correction 3 MISC	OK <sup>-</sup> ABC AFT	TO COVER WHEN REA VE-CEILING SYSTEMS ER TEMP ELECT WIRI	ADY ACT CEILING FRAMING + S @ FOLLOWING SPACES: 105; 108 NG IS REMOVED AND TWO 2x4 LAY-IN TALLED AND SECURED; 111; 112; 113;
	REM TEM WIT	OVED. NOTE THAT SO	ERE ABANDONED PIPING IS TO BE OUTH 15' MAY BE COVERED ON ' PENDING RESOLUTION OF TIE-IN RY USE AREA.
Corrective Action Required 4 MISC Corrective Action Required 6 MISC	REM COM	IOVE ALL ABANDONEI IPONENTS AND HANG	D PIPING AND OTHER SYSTEM SERS @ 109 WEST 8'
	GWI		102 LOBBY NOT PER DRAWING. D WITHOUT A/E DIRECTION.

Comments: