

CITY OF LEE'S SUMMIT CODES ADMINISTRATION 220 SE GREEN ST. P.O.BOX 1600

PHONE: 816-969-1200

FAX:

816-969-1201

Inspection Summary

Permit #: PRCOM20122034, Building Permit - Commercial

Address: 860 NW BLUE PKWY, Unit:T, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

In-wall Inspection John Borns Partial Tuesday, March 05, 2013

Partial Correction

1 MISC OK TO COVER WHEN READY WALL FRAMING + IN-WALL

SYSTEMS AT FOLLOWING SPACES: PERIMETER WALLS AFTER SPRINKLER F.P. PIPE @ EAST WALL IS PROPERLY SECURED; SHOE STORAGE BOTH FACES; WING WALL PER ELEVATION 5/A-4.1 BOTH FACES; N-S WALL AT REAR PASSAGEWAY WHERE ELECTRICAL PANELS ARE TO BE MOUNTED; SALES AREA AND ALL REMAINING EXCEPT REAR (EAST) SPACES;

FITTING ROOM AREA;

Corrective Action Required

2 MISC RESTROOM WALLS: IPC - PROTECTION OF COPPER PIPING AT

PENETRATION OF STEEL FRAMING MEMBERS: INSTALL

GROMMETS OR OTHER APPROVED PROTECTION FROM SHARP

EDGES & DISSIMILAR METAL

Above Ceiling John Borns Partial Tuesday, March 05, 2013 **Inspection**

Partial Correction

1 MISC OK TO COVER WHEN READY GWB CEILING FRAMING +

ABOVE-CEILING SYSTEMS @ FOLLOWING SPACES: OFFICE:

4'x55' CEILING AT FRONT(WEST) OF STORE;

Corrective Action Required

2 MISC DWV PIPING ABOVE RESTROOMS NOT COMPLETED.

Above Ceiling Inspection

Partial Correction

OK TO COVER WHEN READY GWB CEILING FRAMING +
ABOVE-CEILING SYSTEMS @ FOLLOWING SPACES: OFFICE;
4'x55' CEILING AT FRONT(WEST) OF STORE;

Corrective Action Required

2 MISC DWV PIPING ABOVE RESTROOMS NOT COMPLETED.

Comments: