CITY OF LEE'S SUMMIT

CODES ADMINISTRATION DEPARTMENT
220 SE Green Street
Lee's Summit, MO 64063
(816) 969-1200
Fax (816) 969-1201

PLAN REVIEW CONDITIONS

April 05, 2013

SCHARHAG ARCHITECTS 310 ARMOUR RD #218A NORTH KANSAS CITY, MO 64116

Permit No: PRCOM20130503

Project Title: SEARS

Project Address: 232 NW OLDHAM PKWY, LEES SUMMIT, MO 64081

Parcel Number: 62140031600000000

Location: SUMMIT SHOPPING CENTER LOT 1

Type of Work: CHANGE OF TENANT

Occupancy Group: MERCANTILE
Description: TENANT FINISH

The following is a list of requirements from the City of Lee's Summit that have not been satisfactorily addressed in the plans and specifications. Please contact the appropriate department regarding clarification of comments.

Codes Administration (816) 969-1200 Fire Department (816) 969-1300

Licensed Contractors Reviewed By: Michael Weisenborn Pending

1. Lee's Summit Code of Ordinance, Section7-130.10 - Business License. It shall be unlawfull for any person to engage in the construction contracting business without first obtaining a business license as required under the applicable provisions of Chapter 28 of the Lee's Summit Code of Ordinances.

Action required - Provide the name of the licensed general contactor. A minimum of a Class B license is required. This information is required for permit approval.

2. No person, other than a licensed contractor or employees of a licensed contractor, shall engage in electrical, plumbing or mechanical business, construction, installation or maintenance unless duly licensed in accordance with this section. Expert from Sec. 7-130, Lees Summit Code of Ordinances.

Action required - Provide the names of the licensed mechanical, electrical and plumbing contractors. This information is required for permit approval.

Building Plan Review Reviewed By: Michael Weisenborn Rejected

1. 2006 IBC 2406.1 - Human impact loads. Individual glazed areas, including glass mirrors, in hazardous locations as defined in Section 2406.3 shall comply with Sections 2406.1 through 2406.1.4.

Action required - General note 18 on Sheet A2 does not indicate if safety glazing is required in the new storefront. Provide additional information.

2. 2006 IPC 403.4 - Required public toilet facilities. Customers, patrons and visitors shall be provided with public toilet facilities in structures and tenant spaces intended for public utilization. The accessible route to public facilities shall not pass through kitchens, storage rooms, closets or similar spaces. Employees shall be provided with toilet facilities in all occupancies. Employee toilet facilities shall be either separate or combined employee and public toilet facilities.

Action required - This comment is for information purposes.

3. Section 1014.2 has exceptions which allow exiting through storage areas of an M occupancy when all of the conditions are met. One requirement is that the egree door can not be locked to prevent its use. Another is the the path be established by a minimum of a partial height wall

Action required - The plans do not clearly indicate the door hardware to be installed on door 7. Provide additional information on the plans.

We have allowed the floor to be painted indicating that it is an egress path and can not be used for storage. in addition to the striping shown, signage shall be provided indicating that it is an egress path and to be used for storage or be blocked. Provide additional information on the plans.

Fire Plan Review Reviewed By: Brian Austerman Approved with Conditions

1. 2006 IFC 505.1- Address numbers. New and existing buildings shall have approved address numbers, building numbers or approved building identification placed in a position that is plainly legible and visible from the street or road fronting the property. These numbers shall contrast with their background. In Multi-tenant commercial building where tenants have multiple entrances located on different sides of the building, each door shall be addressed. Address numbers shall be Arabic numerals or alphabet letters. Numbers shall be a minimum of 4 inches (102 mm) high with a minimum stroke width of 0.5 inch (12.7 mm).

Provide addressing on all exterior doors leading into the space. Verified at inspection

2. 2006 IFC 510.1- Identification. Fire protection equipment shall be identified in an approved manner. Rooms containing controls for air-conditioning systems, sprinkler risers and valves, or other fire detection, suppression or control elements shall be identified for the use of the fire department. Approved signs required to identify fire protection equipment and equipment location, shall be constructed of durable materials, permanently installed and readily visible.

Verify that the FDC signage on the front wall of the store is still present. Verified at inspection

3. 2006 IFC 901.2- Construction documents. The fire code official shall have the authority to require construction documents and calculations for all fire protection systems and to require permits be issued for the installation, rehabilitation or modification of any fire protection system. Construction documents for fire protection systems shall be submitted for review and approval prior to system installation.

Provide plans for sprinkler work for approval

4. 2006 IFC 907.1.1- Construction documents. Construction documents for fire alarm systems shall be submitted for review and approval prior to system installation. Construction documents shall include, but not be limited to, all of the following: 1. A floor plan which indicates the use of all rooms. 2. Locations of alarm-initiating and notification appliances. 3. Alarm control and trouble signaling equipment. 4. Annunciation. 5. Power connection. 6. Battery calculations. 7. Conductor type and sizes. 8. Voltage drop calculations. 9. Manufacturers, model numbers and listing information for equipment, devices and materials. 10. Details of ceiling height and construction. 11. The interface of fire safety control functions.

Provide alarm plans for approval

The review conducted by the City of Lee's Summit Codes Administration Department shall not be construed as a structural review of the project.