



LEE'S SUMMIT, MISSOURI FIRE DEPARTMENT LOSS REDUCTION PROGRAM



NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

☐ CHANGES

BUSINESS NAME	INFUSION BAR & GRILL		
ADDRESS	837 SW LEMANS LN, LEES SUMMIT, MO 64082		
OWNER/OPERATOR NAME	BAKER BROTHERS CONTRACTORS:	TELEPHONE	(816) 461-6629
ADDRESS	205 E ST CHARLES AVE INDEPENDENCE, MO 64050 Primary: (816) 461-6629 Cell: (816) 918-6629		

EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1.	
2.	
3.	
4.	

LOSS REDUCTION TYPE

<input checked="" type="checkbox"/> Occupancy	<input type="checkbox"/> Semi-Annual	<input type="checkbox"/> Annual	<input type="checkbox"/> Life Safety	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Hazardous Material Permit
<input type="checkbox"/> Complaint	<input type="checkbox"/> Explosive Storage	<input type="checkbox"/> UST	<input type="checkbox"/> Post-Incident	<input type="checkbox"/> Open Burning	<input type="checkbox"/> Other
CLASS: A-2	Map#: 215A	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT # PRCOM20130151

LOSS REDUCTION NARRATIVE

☐ NO VIOLATIONS NOTED

☐ ALL VIOLATIONS RESOLVED

Last Inspection

1st Inspection

2nd Inspection

3rd Inspection

4th Inspection

INSPECTION	INSPECTOR	OUTCOME	DATE
Alarm Test	Joe Dir	Not Required	Friday, April 19, 2013
Sprinkler - Hydrostatic Test	Joe Dir	Not Required	Friday, April 19, 2013
Sprinkler - Flow Test	Joe Dir	Not Required	Friday, April 19, 2013
Occupancy Inspection - Fire	Joe Dir	Temporary C of O	Friday, April 19, 2013
Corrective Action Required:			
1 -post occupant loads in bar / dining area and patio area -need fire extinguisher in cabinet located by the bar, rated 2A-10BC minimum - proper nozzel placement under hood once appl. are set under the hood			

- check all of the exit and emergency lighting for battery operation

DATE OF REPORT	INSPECTOR	PREVENTION FOLLOW-UP REQUIRED?	RESPONSIBLE SIGNATURE
April 19, 2013	Joe Dir	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	