



LEE'S SUMMIT, MISSOURI FIRE DEPARTMENT LOSS REDUCTION PROGRAM



NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

☐ CHANGES

BUSINESS NAME	JOHN KNOX VILLAGE SOLAR ARRAY		
ADDRESS	512 NW MURRAY RD, LEES SUMMIT, MO 64081		
OWNER/OPERATOR NAME	BRIGHTERGY LLC:	TELEPHONE	(913) 735-9733
ADDRESS	15209 W 99TH ST LENEXA, KS 66219 Primary: (913) 735-9733 Cell: (206) 718-7416		

EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1.	
2.	
3.	
4.	

LOSS REDUCTION TYPE

<input type="checkbox"/> Occupancy	<input type="checkbox"/> Semi-Annual	<input type="checkbox"/> Annual	<input type="checkbox"/> Life Safety	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Hazardous Material Permit
<input type="checkbox"/> Complaint	<input type="checkbox"/> Explosive Storage	<input type="checkbox"/> UST	<input type="checkbox"/> Post-Incident	<input type="checkbox"/> Open Burning	<input checked="" type="checkbox"/> Other
CLASS: I-2	Map#: 195E	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT #

LOSS REDUCTION NARRATIVE

☐ NO CORRECTIONS NOTED

☐ ALL CORRECTIONS COMPLETED

Last Inspection

1st Inspection

2nd Inspection

3rd Inspection

4th Inspection

DEC. 30, 2011

INSPECTION	INSPECTOR	OUTCOME	DATE
Occupancy Inspection - Fire	Jim Eden	Temporary C of O	Friday, December 30, 2011
Corrective Action Required:			
1 Label the outside of 3rd floor middle panel and panel HB-3B with proper solar circuit markings.			
Corrective Action Required:			
2 Label the inverter and inverter disconnects with address labels.			
DATE OF REPORT	INSPECTOR	PREVENTION FOLLOW-UP REQUIRED?	RESPONSIBLE SIGNATURE
December 30, 2011	Jim Eden	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	