



LEE'S SUMMIT, MISSOURI FIRE DEPARTMENT LOSS REDUCTION PROGRAM



NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

☐ CHANGES

BUSINESS NAME	ROCKHILL ORTHOPAEDICS		
ADDRESS	120 NE SAINT LUKES BLVD, Unit:200, LEES SUMMIT, MO 64086		
OWNER/OPERATOR NAME	MCCOWN GORDON CONSTRUCTION:	TELEPHONE	(816) 960-1111
ADDRESS	422 ADMIRAL BLVD SUITE 100 KANSAS CITY, MO 64106--1560 Primary: (816) 960-1111 Cell: <NO CELL PHONE>		

EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1.	
2.	
3.	
4.	

LOSS REDUCTION TYPE

<input checked="" type="checkbox"/> Occupancy	<input type="checkbox"/> Semi-Annual	<input type="checkbox"/> Annual	<input type="checkbox"/> Life Safety	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Hazardous Material Permit
<input type="checkbox"/> Complaint	<input type="checkbox"/> Explosive Storage	<input type="checkbox"/> UST	<input type="checkbox"/> Post-Incident	<input type="checkbox"/> Open Burning	<input type="checkbox"/> Other
CLASS: B	Map#: 175X	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT # prcom20121479

LOSS REDUCTION NARRATIVE

NO VIOLATIONS NOTED

☐ **ALL VIOLATIONS RESOLVED**

Last Inspection

1st Inspection

2nd Inspection

3rd Inspection

4th Inspection

INSPECTION	INSPECTOR	OUTCOME	DATE
Alarm Test	Joe Dir	Passed	Tuesday, February 19, 2013
Alarm Test	Joe Dir	Passed	Monday, November 26, 2012
Sprinkler - Hydrostatic Test	Joe Dir	Passed	Friday, January 04, 2013
Sprinkler - Flow Test	Joe Dir	Passed	Friday, January 04, 2013
Occupancy Inspection - Fire	Joe Dir	Temporary C of O	Tuesday, November 27, 2012
Corrective Action Required:			

- 1 -extend sprinkler coverage into the transitional areas: Exam 2E131, 2E64
-addressing off the corridors

Alarm Test Joe Dir Passed Friday, January 04, 2013

Occupancy Inspection - Fire Joe Dir Temporary C of O Monday, January 07, 2013

Corrective Action Required:

- 1 -extend sprinkler coverage into the transitional areas: Exam 2E131, 2E64
-addressing off the corridors

Occupancy Inspection - Fire Joe Dir Temporary C of O Monday, January 14, 2013

Corrective Action Required:

- 1 -extend sprinkler coverage into the transitional areas: Exam 2E131, 2E64
-addressing off the corridors

Corrective Action Required:

- 2 PHASE 2B
-cast room 2E128 needs sprinkler head eschution installed
-secure all ceiling tile throughout rennovation area
- remove all construction materials, tools and debris from rooms and corridors
- label appropriate doors from corridor with the proper numerics/addressing

Occupancy Inspection - Fire Brian Austerman Passed Friday, February 01, 2013

Corrective Action Required:

- 1 -extend sprinkler coverage into the transitional areas: Exam 2E131, 2E64
-addressing off the corridors

Corrective Action Required:

- 2 PHASE 2B
-cast room 2E128 needs sprinkler head eschution installed
-secure all ceiling tile throughout rennovation area
- remove all construction materials, tools and debris from rooms and corridors
- label appropriate doors from corridor with the proper numerics/addressing

Occupancy Inspection - Fire Joe Dir Passed Tuesday, February 19, 2013

PHASE-2C(2/19/13) Ok to occupy once cleared through codes administration

DATE OF REPORT	INSPECTOR	PREVENTION FOLLOW-UP REQUIRED?	RESPONSIBLE SIGNATURE
February 19, 2013	Joe Dir	<input type="checkbox"/> Yes <input type="checkbox"/> No	