

CITY OF LEE'S SUMMIT CODES ADMINISTRATION 220 SE GREEN ST. P.O.BOX 1600

PHONE: 816-969-1200

FAX: 816-969-1201

## Inspection Summary

Permit #: PRCOM20131937, Building Permit - Commercial Address: 228 NW OLDHAM PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
In-wall Inspection	John Borns	Failed	Thursday, January 09, 2014
Corrective Action Requ 1 MISC	IPC - STEI APPI	EL FRAMING MEMBERS ROVED PROTECTION F	PER PIPING AT PENETRATION OF : INSTALL GROMMETS OR OTHER ROM SHARP EDGES & DISSIMILAR
Corrective Action Requ 2 MISC Corrective Action Requ 3 MISC	ired IPC 3 / ABS FACI COV HAR COV PENI ABO TRAC ABO TRAC DEFI	METAL. IPC 305.8; IRC P2603 PROTECTION FROM PENETRATION OF PVC / ABS / PEX / COPPER PLUMBING PIPE LESS THAN 1-1/2" FROM FACE OF FRAMING TO RECEIVE SCREWED OR NAILED COVERING: PROTECT PIPE WITH MINIMUM 1/16" THICK HARDENED STEEL SHIELD PLATES. SHIELD PLATES SHALL COVER THE AREA OF THE MEMBER WHERE THE PIPE PENETRATES. SHIELD PLATES SHALL EXTEND A MINIMUM OF 2" ABOVE BASE PLATES / TRACKS AND BELOW TOP PLATES / TRACKS (USE "BOCA" PLATES). CHECK ALL. MOUNTING OF IN-WALL ELECTRICAL BOXES: SECURE AGAINST DEFLECTION. USE STAND-OFFS OR EQUAL TO PREVENT MOVEMENT OF BOX.	
Above Ceiling Inspection	John Borns	Partial	Thursday, January 09, 2014
Partial Correction 1 MISC	-		Y GWB CEILING FRAMING + @ FOLLOWING LOCATIONS: SOFFIT

## AT 116 W WALL; SOFFIT AT 115 VERTICAL FACES ONLY;

Comments: