

CODES ADMINISTRATION

Inspection Summary

Permit #: PRCOM20131937, Building Permit - Commercial Address: 228 NW OLDHAM PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Above Ceiling Inspection	John Borns	Partial	Tuesday, January 21, 2014
Partial Correction 1 MISC	SYSTEI		3 CEILING FRAMING + ABOVE-CEILING DNS: SOFFIT AT 116 W WALL; SOFFIT AT 115; 3;

Comments: