

CODES ADMINISTRATION

Inspection Summary

Permit #: PRCOM20132180, Building Permit - Commercial Address: 100 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | Inspector: | Outcome: | Date: | |
|------------------------------|--|--|---|--|
| Above Ceiling Inspection | John Borns | Partial | Wednesday, February 12, 2014 | |
| Partial Correction | | | | |
| 1 MISC | SYSTEI (16.4), LID 11 | OK TO COVER WHEN READY GWB CEILING FRAMING + ABOVE-CEILING SYSTEMS @ FOLLOWING SPACES:SOFFITS AT CORRIDORS 203 & 207 @ (16), (16.4), (18.1), (18.4); LOBBYS 200 & 204; NURSE STATION 150 SOFFITS; HARD LID 11' AFF @ ELEV LOBBY 200; OVAL FACIA @ 9'-8"; ARC SOFFITS FROM C'/11 TO C/9 AND FROM A.8/10.5 TO A.8/9.5; | | |
| Partial Correction | | | | |
| 2 MISC Partial Correction | OK TO COVER WHEN READY SHOWER LIDS AT: 031 THRU 060; | | | |
| 3 MISC | | VIS @ FOLLOWING SPACES: | CEILING FRAMING + ABOVE-CEILING : 5A047-062; 5A135-137; 139; 141; 143; | |

Comments: