

## Inspection Summary

Permit #: PRCOM20132126, Building Permit - Commercial

Address: 2301 NE INDEPENDENCE AVE, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Above Ceiling Inspection</b>	Khanh Nguyen	Partial	Wednesday, February 12, 2014

Corrective Action Required

1	MISC	-INSTALL RESTROOM EXHAUST -COMPLETE VENTING THROUGH ROOF
---	------	---

**\*\*OK TO DROP TILES, EXCEPT ABOVE 2ND FL RESTROOMS**

**Comments:**