PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20132180, Building Permit - Commercial Address: 100 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Occupancy Inspection - John Borns Not Ready Wednesday, April 23, 2014

Codes Commercial

Corrective Action Required

1 MISC SOME FIRE DOORS DO NOT DISPLAY UL LABELS

Corrective Action Required

2 MISC 18" VERTICAL SIDEWALL GRAB BARS MIS-LOCATED AT TOILET ROOMS

5A061A; 063; 133; 134

Corrective Action Required

3 MISC TWO ELECT RECEPTS @ 5A136 WITHIN 6' OF EDGE OF SINK NEED TO BE GFCI

PROTECTED.

Corrective Action Required

4 MISC CRITICAL CIRCUIT ELECT RECEPTS @ IT 5A070 YET TO BE TESTED WHEN

CIRCUITS ARE HOT

Corrective Action Required

5 MISC OCCUPANCY STATUS:

RT 5A117/118 OK FOR TEMPORARY OCCUPANCY CONTINGENT ON SCHEDULED COMPLETION AND APPROVAL OF FIRE COMMAND SYSTEM. REMAINDER OF SPACES OK TO SET UP FOR BUSINESS. NO PATIENTS NOR

PUBLIC PRIOR TO APPROVAL.

Comments: