

PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20140176, Building Permit - Commercial
Address: 880 NW BLUE PKWY, Unit:C, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Commercial	John Borns	Failed	Monday, May 12, 2014

Corrective Action Required

1 MISC

INSTALLATION OF LIGHTED SIGN SUBJECT TO APPROVAL WHEN INSTALLED. PER NEC 600.3, IF INTERNALLY LIGHTED MUST BE SHOP-LABELED. INSTALL NO NON-LISTED SIGN.

Corrective Action Required

2 MISC

LS CODE OF ORDINANCES 17-309: DISPLAY OF "NO SMOKING" SIGN(S) REQUIRED AT PUBLIC ENTRY(IES). SHALL BE CONSPICUOUS AT EACH PUBLIC POINT OF ENTRY.

Corrective Action Required

3 MISC

NEC 406.8; E3902.8: IN-USE WEATHERPROOF COVER REQUIRED ON ELECTRICAL RECEPTACLES AT WET LOCATIONS. SEE AT RTU.

Corrective Action Required

4 MISC

GFI ELECT RECEPT AT RTU NO TRIPPING ON TEST

Corrective Action Required

5 MISC

GFI ELECT RECEPTS AT RESTROOMS NOT TRIPPING; SIMILAR AT STOCK ROOM.

Corrective Action Required

6 MISC

LOOSE ELECT RECEPTS: [100] N.E. & S.E.

Corrective Action Required

7 MISC

FLOOR SINK IN "MENS" NOT SEALED AT PERIMETER

Corrective Action Required

8 MISC

ANSI 603.3 MOUNTING OF MIRRORS AT ACCESSIBLE RESTROOMS: SET BOTTOM OF VIEWING SURFACE \leq 40" AFF.

Corrective Action Required

9 MISC

ENSURE ELECT PANEL SCHEDULES ARE COMPLETE, CORRECT, CLEAR AND LEGIBLE. ALSO LABEL PANEL FRONTS.

Corrective Action Required

10 MISC

OCCUPANCY STATUS: OK TO SET UP FOR BUSINESS. NO PUBLIC NOR CUSTOMERS PRIOR TO APPROVAL.

**Gas Service Inspection - John Borns
Commercial**

Passed

Monday, May 12, 2014

Comments: