
PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRPWFR20141829, Public Works Infrastructure Permit - Residential
Residences at New Longview
Address: 3301 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

| Inspection: | Inspector: | Outcome: | Date: |
|--|------------|----------|---------------------------|
| PW-Sanitary Sewer Construction Inspection Corrective Action Required | Jon Haley | Partial | Tuesday, July 15, 2014 |
| 1 Tied into manhole and laid two sticks out of manhole. | | | |
| Corrective Action Required | | | |
| 2 Laid from MH A3 to A4 | | | |

Comments:
