

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRPWFR20141829, Public Works Infrastructure Permit - Residential

Residences at New Longview

Address: 3301 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:			
Inspection:	Inspector:	Outcome:	Date:
PW-Sanitary Sewer	Jon Haley	Passed	Friday, July
Construction Inspection	·		18, 2014
Corrective Action Required			

I arrived on site today and found the contractord laid on e sewer stub out of mh A5 to building 2. I told him to stop. I called Mark H and he said if i looked at this one okay to backfill but no more.

Comments: