

CODES ADMINISTRATION

Inspection Summary

Permit #: PRCOM20140090, Building Permit - Commercial Address: 100 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Above Ceiling John Borns Partial Wednesday, August 13, 2014

Inspection

Corrective Action Required

1 Misc 1 PHASE 2 KITCHEN AREA: **REMOVE ANY UNUSED / ABANDONED HANGERS**

AND BRACES. EXAMPLE -- ALL-THREAD ROD HANGERS AT SELF-SERVE AND

AT NW CORNER

Comments: