

#### **PUBLIC WORKS ENGINEERING DIVISION**

# **Public Works Site Visit**

Permit #: PRPWFR20141829, Public Works Infrastructure Permit - Residential

Residences at New Longview

Address: 3301 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item: Inspection:	Inspector:	Outcome:	Date:
PW-Site Visit	Jon Haley	Partial	Friday, September 26, 2014

## Corrective Action Required

A water truck is needed to keep dirt and dust from leaving your site. All attempts should be made to keep this from happening.

## Corrective Action Required

Went and looked at domestic water meter vault. 3" water line, told the contractor i would psi test the line and pull bac t samples. But mark would continue to look at construction of the line.

# Corrective Action Required

3 Spoke with contractor about testing and water shut down. Went over about the next two weeks plans.

PW-Site Visit	Jon Haley	Partial	Friday,
			September
			26 2014

#### Corrective Action Required

A water truck is needed to keep dirt and dust from leaving your site. All attempts should be made to keep this from happening.

## Corrective Action Required

Went and looked at domestic water meter vault. 3" water line, told the contractor i would psi test the line and pull bac t samples. But mark would continue to look at construction of the line.

## Corrective Action Required

3 Spoke with contractor about testing and water shut down. Went over about the next two

Commontin	Weeks plans.
4	e Action Required Shawn calle dasked about city sidewalk, told wa610 1-4 mix
4	Shawn calle dasked about city sidewark, told waoto 1-4 lilix
Commen	ts: