March 26, 2015

City of Lee's Summit Codes Administration P.O. Box 1600 Lee's Summit, Missouri 64063

Attention:

Mr. Mike Weisenborn

RE:


Special Inspection Services

Sky Zone Shell

Lee's Summit, Missouri

Mr. Weisenborn:





testing services in conjunction with Special Inspection Requirements of the 2012 IBC for the following items. INSPECTION OF WOOD FABRICATION INSPECTION OF PIER FOUNDATIONS PROCESS per 1704.2 per 1704.9 INSPECTION OF STEEL FABRICATION INSPECTION OF PILE FOUNDATIONS П PROCESS per 1704.3 per 1704.8 INSPECTION OF CONCRETE per table 1704.4 INSPECTION OF STEEL per table 1704.3  $\boxtimes$ Inspection of reinforcing steel, including Material verification of high-strength bolts, nuts pre-stressing tendons and placement and washers  $\boxtimes$ Inspection of bolts installed in concrete prior to Inspection of high strength bolts and during placement of concrete where Inspection of field welding allowable loads have been increased. Inspection of steel frame joint details for Verifying use of required design mix (Required) compliance with approved construction  $\overline{\boxtimes}$ Sampling fresh concrete and performing slump, documents (Required) air content and determining the temperature of fresh concrete at the time of making specimens INSPECTION OF EXTERIOR INSULATION for strength tests. (Required) AND FINISH SYSTEMS (EIFS) per 1704.12 X Inspection of concrete and shotcrete placement for proper application techniques (Required) **INSPECTION OF MASONRY per 1704.5** X Inspection for maintenance of specified curing and temperature control techniques. (Required) Empirically designed masonry, glass unit masonry Inspection of post-installed anchors and masonry veneer Inspection of pre-stressed concrete (essential facilities) per 1704.5.1 Engineered masonry in nonessential facilities Erection of pre-cast П Verification of in-situ, concrete strength, prior to per 1704.5.2 Engineered masonry in essential facilities stressing of tendons in post-tensioned concrete and prior to removal of shores and forms from per 1704.5.3 beams and structural slabs. INSPECTION OF SPRAYED FIRE RESISTIVE INSPECTION OF SOIL CONDITIONS per table 1704.7 MATERIALS per 1704.11  $\boxtimes$ INSPECTION OF SMOKE CONTROL SYSTEM Verification of foundation bearing materials per 1704.114 Verification of engineered fill placement If there are any questions with regard to this letter, or if we can be of further service in any way, please do

Terracon has been retained by Little Dixie Construction LLC to provide construction observation and

Andrew L. Smith, PE

Sincerely

not hesitate to contact us.

Project Managererracon Consultants, Inc. 13910 West 96th Terrace Lenexa, Kansas 66215

P [913] 492 7777 F [913] 492 7443 terracon.com

