## PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

## Inspection Summary

Permit #: PRCOM20141078, Building Permit - Commercial Address: 3351 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:	
Rated Assembly Inspection	Mark Hardin	g Partial	Friday, April 24, 2015	
Corrective Action Require 1 FIRST FLOOR		LST LAYER		
Corrective Action Required 2 SECOND FLOOR		CORRIDOR-1ST OK		
Corrective Action Required 3 THIRD FLOOR Corrective Action Required 4 FOURTH FLOOR		CORRIDOR-2ND LAYER OK CORRIDOR 1,2, OK CAULK GAPS ON 2ND		
	I	ROOMS - CEILING OF 4TH	FLOOR OK EXECPT 1406 GAP IN ROCK	
Corrective Action Required 5 LOWER LEVEL		RATED CEILING - 2ND LAYER OK , EXCEPT OUTSIDE IT ROOM. EAST END OF CORRIDOR NEEDS SHEETROCKED WHEN PIPES ARE DROPED FROM CEILING.		
Corrective Action Require 6 B705 FIRE WA	LLS		OR 2ND LAYER APPROVED 1,2,3 FLOORS LING NEED FIXEDS AND NAILED AT EACH LEVEL OK	

## SOUTH STAIR-OK TO INSTALL 1 OF 4 LAYER ON CEILING

Comments: