## PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

## Inspection Summary

## Permit #: PRCOM20141078, Building Permit - Commercial Address: 3351 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Above Ceiling Inspection		Inspector:	Outcome:	Date:		
		Mark Harding	Partial	Tuesday, May 19, 2015		
Corrective Action Required 1 LOWER LEVEL			GARAGE - CORRIDOR			
2	ve Action Require FIRST FLOOR ve Action Require SECOND FLOO	COMI	COMPLETE CORRIDOR ceiling failed holes cut in both layers			
3	SECOND FLOO	K CORR	IDOR Celling Talle	ed holes cut in both layers		
Correctiv 4	ve Action Require THIRD FLOOR	ed 3rd fl	OUT AND PATCH oor lor ok to rock	, SHAWN -NICK		
Corrective Action Required 5 FOURTH FLOOR Corrective Action Required		R DROP	DROP DOWNS AND CORRIDOR OK TO ROCK			
6	Misc 1	FURN IT RO CAUL		R ROOMS, ALL NEED INSPECTED FOR FINAL COVER A	٧D	
Above Ceiling Mark Hard Inspection		Mark Harding	Partial	Tuesday, May 19, 2015		
Correctiv	e Action Require	ed				
1	Misc 1		SPECTION 5-18			

Comments: