PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20150580, Building Permit - Commercial Address: 910 NW BLUE PKWY, Unit:J, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Rated Assembly John Borns Failed Wednesday, June 10, 2015

Inspection

Corrective Action Required

1 Misc 1 CORRECT FASTENER PATTERN TO 8"&12" EVERYWHERE INCLUDING BOTTOM

OF STUDS AND AT PANEL JOINTS.

Corrective Action Required

2 Misc 1 INTEGRITY OF GWB AND FASTENER PATTERN UNKNOWN WHERE ELECTRICAL

BACKBOARD WAS INSTALLED PRIOR TO INSPECTION.

Comments: