

PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20150580, Building Permit - Commercial
Address: 910 NW BLUE PKWY, Unit:J, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Underslab Electrical Inspection - Commercial	John Borns	Passed	Wednesday, June 10, 2015

Rated Assembly Inspection	John Borns	Failed	Wednesday, June 10, 2015
----------------------------------	------------	--------	--------------------------

Corrective Action Required

1 Misc 1

CORRECT FASTENER PATTERN TO 8" & 12" EVERYWHERE INCLUDING BOTTOM OF STUDS AND AT PANEL JOINTS.

Corrective Action Required

2 Misc 1

INTEGRITY OF GWB AND FASTENER PATTERN UNKNOWN WHERE ELECTRICAL BACKBOARD WAS INSTALLED PRIOR TO INSPECTION.

Underslab Plumbing Inspection - Commercial	John Borns	Passed	Wednesday, June 10, 2015
---	------------	--------	--------------------------

Comments: UNDER-SLAB ELECTRICAL CONDUIT TO POINT-OF-SERVICE. UNDER-SLAB DWV PLUMBING PIPING AT RESTROOM AND WATER COOLER.