PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20141078, Building Permit - Commercial Address: 3351 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:	
Occupancy Inspection - Codes Commercial	Mark Harding	Temporary C of O	Monday, June 15, 2015	
Corrective Action Require	ed			
1 Misc 1	- SEE UNIT 1ST F -1101 2ND	APPROVED FOR TCO - SEE OTHER DEPARTMENTS FOR APPROVAL UNITS APPROVED 1ST FLOOR -1101,1102 ONLY 2 UNITS WITH OUT KITCHEN CABINETS AND COUNTERS. 2ND FLOOR-2 EAST END UNITS- OTHER OK NO INSPECTION ON 3,4 FLOORS		
		NOT TO OCCUPY ANY UNITS 3-4 FLOORS ALL STAIRWAYS AND CORRIDORS MUST REMAIN CLEAR FOR OCCUPANTS.		
Corrective Action Require 2	ed			
Occupancy Inspection - Codes Commercial	Mark Harding	Failed	Monday, June 15, 2015	
Corrective Action Require	ed			
1 Misc 1	APPR - SEE UNIT 1ST F -1101 2ND	APPROVED FOR TCO - SEE OTHER DEPARTMENTS FOR APPROVAL UNITS APPROVED 1ST FLOOR -1101,1102 ONLY 2 UNITS WITH OUT KITCHEN CABINETS AND COUNTERS. 2ND FLOOR-2 EAST END UNITS- OTHER OK NO INSPECTION ON 3,4 FLOORS		
		NOT TO OCCUPY ANY UNITS 3-4 FLOORS ALL STAIRWAYS AND CORRIDORS MUST REMAIN CLEAR FOR OCCUPANTS.		

 Corrective Action Required

 2
 Misc 1

 Occupancy inspection for 1078 3351 sw kesselr.

 1st floor model was complete, 1102 no cabinets or counter/sink.

 2nd floor was incomplete 2-end units. 1202 faucet was in but drainage was incomplete.

 1201 same

Comments: