

PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20141074, Building Permit - Commercial
Address: 3311 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	Mark Harding	Partial	Friday, July 17, 2015

Corrective Action Required

1	Misc 1	1st layer elevator walls failed needs screw rear of wall at corners dryer vent boxes- -TUB WALLS - 4101 CAULK 2ND-FAILED-4213,4205, 3RD-FAILED-4309, 4TH FAILED-12,08,09,00,07,01 TUBS 4211-4412 TUBS DIDNT PASS 2ND LAYER TUBWALL 2HRS- 4,3,2
---	--------	---

Corrective Action Required

2 FIRST FLOOR

Corrective Action Required

3 SECOND FLOOR

Corrective Action Required

4 THIRD FLOOR

All Rough Inspection - Commercial	Mark Harding	Failed	Friday, July 17, 2015
--	--------------	--------	-----------------------

Corrective Action Required

1	LOWER LEVEL	4000 LINE SETS CAULK TRUCK LINE INCOMPLETE -
---	-------------	--

Corrective Action Required

2	FIRST FLOOR	4100,4112
---	-------------	-----------

Corrective Action Required

3	SECOND FLOOR	NOT READY HVAC INCOMPLETE
---	--------------	---------------------------

Comments: