

PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20150014, Building Permit - Commercial
Address: 508 NW MURRAY RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	John Borns	Partial	Thursday, August 13, 2015
Partial Correction 1 Misc 1		1ST FLOOR: OK TO TAPE, MUD & FIRE-STOP PRE-ROCK: UNIT 113: GWB WALL AT DEAD SPACE ADJACENT TO CORRIDOR; UNIT 112: LID OF CLOSET AT EXT WALL; UNIT 132: CEILING ABOVE HVAC DUCT AT BR; UNITS 101 & 102: CORR WALL @ COAT CLO;	
Partial Correction 2 Misc 1		2ND FLOOR: CORRIDOR CEILING SINGLE LAYER 5/8" TYPE X GWB OK TAPE, MUD, & FIRE-SEAL.	
Partial Correction 3 Misc 1		3RD FLOOR: CORRIDOR CEILING SINGLE LAYER 5/8" TYPE X GWB OK TAPE, MUD, & FIRE-SEAL. NOTE: PENETRATION BY 4" PVC DRAIN LINE NOT APPROVED. REFER TO DRAWINGS/SPECS OR REQUEST WRITTEN DIRECTION FROM A/E.	
All Rough Inspection - Commercial	John Borns	Partial	Thursday, August 13, 2015
Partial Correction 1 Misc 1		1ST FLOOR: OK TO COVER EXTERIOR WALLS; UNIT WALLS;	
Partial Correction 2 Misc 1		2ND FLOOR: OK TO COVER CORRIDOR CEILING; AFTER ALL HOLD-DOWNS ARE TORQUED AND ALL FIRE-BLOCKING IS FULLY SEALED, OK TO COVER WALLS EXCEPT AT ELECTRICAL PANELS;	
Corrective Action Required 3 Misc 1		3RD FLOOR: OK TO COVER CORRIDOR CEILING	

Comments: