PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20141080, Building Permit - Commercial Address: 3371 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Mark Harding Partial Monday, August 24, 2015

Commercial

Corrective Action Required

1 LOWER LEVEL GARAGE SIDE OK

Corrective Action Required

2 SECOND FLOOR -bond metal pancake boxes in bathrooms

-complete laundry vent cut in

-5210-strap other side 3" pvc, puddy pad bathroom van light,

5209-nail strap roof drain 5205- south bed wall nail straps

5202-firestop 3 " pipe

5201-firestop 3" pipe, protect grey water line, hvac incomplete

Corrective Action Required

3 THIRD FLOOR 5302-mastic on joint duct,

5301-firestop roof drain nail straps, double slant wall for truss bearing, seal

bath fan joints 5303-duct joints 5304-duct joint

5305-draftsstop north wall, nail straps, duct joint mastic

5307-draftsstop south wall, re do hvac so complys with separation between

units, duct joints, firestop roof drain and nail straps

5308-duct joints, puddy pad north bath 5309-nail straps roof drain, joint sealant 5310-strap mid top plate, duct joints 5312-firestop dryer vent, duct joint 5314-hvac incomplete, firestop laundry

Comments: