## PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

## Inspection Summary

## Permit #: PRCOM20141080, Building Permit - Commercial Address: 3371 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	Mark Harding	Failed	Tuesday, August 25, 2015
Corrective Action Require LOWER LEVEL Corrective Action Require SECOND FLOO Corrective Action Require THIRD FLOOR	GARA ed R ed 5302- 5301-	GARAGE SIDE OK 5302-mastic on joint duct, 5301-firestop roof drain nail straps, double slant wall for truss bearing, seal	
	5303- 5304- 5305- 5307- units, 5308- 5309- 5310- 5312-	bath fan joints 5303-duct joints 5304-duct joint 5305-draftsstop north wall, nail straps, duct joint mastic 5307-draftsstop south wall, re do hvac so complys with separation between units, duct joints, firestop roof drain and nail straps 5308-duct joints, puddy pad north bath 5309-nail straps roof drain, joint sealant 5310-strap mid top plate, duct joints 5312-firestop dryer vent, duct joint 5314-hvac incomplete, firestop laundry	
Corrective Action Require 4 FOURTH FLOO	R WIRE		5, 4" ROOF DRAIN CAULK NAIL STRAPS, ALL BOXES, NAIL PLATES FOR PLUMBING.

Comments: