

PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20150014, Building Permit - Commercial
Address: 508 NW MURRAY RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	John Borns	Partial	Thursday, September 17, 2015

Partial Correction
1 Misc 1

1ST FLOOR:
OK TO TAPE, MUD & FIRE-STOP:
RATED CEILINGS AND WALLS AT ALL UNITS EXCEPT STAIRWELL
WALLS; ELEVATOR MACHINE ROOM; NO OTHER COMMON OR
UTILITY AREAS

PRE-ROCK:
UNIT 113: GWB WALL AT DEAD SPACE ADJACENT TO CORRIDOR;
UNIT 112: LID OF CLOSET AT EXT WALL; UNIT 132: CEILING ABOVE
HVAC DUCT AT BR; UNITS 101 & 102: CORR WALL @ COAT CLO;

Partial Correction
2 Misc 1

2ND FLOOR: OK TO TAPE, MUD & FIRE-STOP:
- CORRIDOR CEILING AND WALLS ONE LAYER 5/8" TYPE X GWB
- RATED CEILINGS AND WALLS AT ALL UNITS EXCEPT WALLS AT
STAIRWELLS

Partial Correction
3 Misc 1

3RD FLOOR: OK TO TAPE, MUD & FIRE-STOP ONE LAYER 5/8" TYPE
X GWB AT: CORRIDOR CEILING; ELECT & DATA RMS WALLS.
WALLS AND CEILINGS AT UNITS 302*; 311; 312*; 313; 314; 315;
317; 318; 321; 323; 324; 327; 332; 333; CORRIDOR WALLS EXCEPT
AT ROOF DRAINS;

*EXCEPT ROOF DRAINS & STAIRWELL WALLS

STAIRWELL WALLS NOT READY FOR INSPECTION

Partial Correction
4 Misc 1

4TH FLOOR: OK TO TAPE, MUD & FIRE-STOP ONE LAYER 5/8"
TYPE X GWB AT: UNITS 412; 413*; 414*; 423; 424; 427*;

***CONDITION: CHASE TO BE CONSTRUCTED AT FIRE SPRINKLER
LINES**

Comments: