PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20141077, Building Permit - Commercial Address: 3341 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Mark Harding Failed Wednesday, September 23,

Commercial 2015

Corrective Action Required

1 FIRST FLOOR RE-INSPECTION

NORTH END UNIT DRYER BOX, HVAC,

Corrective Action Required

2 SECOND FLOOR truss fix,

Corrective Action Required

3 THIRD FLOOR 6313 -nail straps

caulk at vent pipe chase around rock

sail plate sprinkler pipe 6312 - nail straps 6311-gusset off truss

hole at roof drain repair floor fireseal box bedroom wall not made up

6308 studs with cut in kitchen /corridor wall

fire caulk all google penatrations throughout.

Comments: