PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20150014, Building Permit - Commercial Address: 508 NW MURRAY RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:	
All Rough Inspection - Commercial	John Borns	Partial	Wednesday, September 30, 2015	
Partial Correction				
1 Misc 1		1ST FLOOR: OK TO COVER WHEN READY: EXTERIOR WALLS; UNIT WALLS; CORRIDOR CEILING AND WALLS; CEILING AT SPACE 111; ABOVE-CEILING AND OSB WALL SHEATHING OK TO COVER WHEN READY AT 119 & 120 EXCEPT DO NOT COVER PENETRATIONS UNTIL APPROVED PER UL DESIGN TO BE SPECIFIED BY A/E;		
Partial Correction				
2 Misc 1		2ND FLOOR: OK TO COVER WHEN READY: CO WALLS EXCEPT AT ELEVATOR LO	RRIDOR CEILING; ALL CEILINGS &	
Partial Correction				
3 Misc 1		3RD FLOOR: OK TO COVER WHEN READY: CO WALLS EXCEPT AT STAIRWELLS &	RRIDOR CEILING; ALL CEILINGS & & ELEVATOR LOBBY	
Partial Correction				
4 Misc 1		4TH FLOOR: COMPLETION OF WALL CAVITY I SHIELD/BOCA PLATING OF PLUM COVER WHEN READY ALL CEILIN STAIRWELLS & ELEVATOR LOBBY	IBING LINES IN PROGRESS. OK TO IGS & WALLS EXCEPT AT	
Partial Correction				
5 Misc 1		OK TO COVER WHEN READY OSE EAST STAIRWELL FULL HEIGHT; V		
Rated Assembly Inspection	John Borns	Partial	Wednesday, September 30, 2015	
Partial Correction				

1	Misc 1	1ST FLOOR:
		OK TO TAPE, MUD & FIRE-STOP:
		RATED CEILINGS AND WALLS AT ALL UNITS ELEVATOR MACHINE
		ROOM; E108; CORRIDOR CEILING AND WALLS; 119 EXCEPT
		SOUTH WALL; 120 EXCEPT NORTH WALL;
Partial Co	prrection	
2	Misc 1	2ND FLOOR: OK TO TAPE, MUD & FIRESTOP: CORRIDOR CEILING
		AND WALLS; RATED CEILINGS AND WALLS AT: ALL UNITS; 208;
		219; 220;
Partial Co	prrection	
3	Misc 1	3RD FLOOR: OK TO TAPE, MUD & FIRE-STOP ONE LAYER 5/8" TYPE
		X GWB AT: CORRIDOR CEILING; ELECT & DATA RMS WALLS.
		WALLS AND CEILINGS AT UNITS 302*; 311; 312*; 313; 314; 315;
		317; 318; 321; 323; 324; 327; 332; 333; CORRIDOR WALLS; 319;
		320;
		*FXCEPT ROOF DRAINS & STAIRWELL WALLS
		STAIRWELL WALLS NOT READY FOR INSPECTION
Partial Co	rrection	STAIRWELE WALLS NOT READ TOR INSPECTION
4	Misc 1	4TH FLOOR: OK TO TAPE, MUD & FIRE-STOP ONE LAYER 5/8" TYPE
4	IVIISC 1	
		X GWB AT: UNITS 412; 413*; 414*; 423; 424; 427*; CORRIDOR
Composition	a Action Dequined	WALLS ONLY ; E428; E429; [411; 419; 420;
	e Action Required	
5	Misc 1	PROTECTION OF PENETRATIONS TO BE SPECIFIED BY A/E;

Comments: