



VAN DEURZEN AND ASSOCIATES, P.A.
CONSULTING STRUCTURAL ENGINEERS
11011 KING STREET, SUITE 130
COMMERCE TERRACE BUILDING D
OVERLAND PARK, KANSAS 66210
(913) 451 - 6305 FAX (913) 451 - 1021

October 5, 2015

Mr. E.J. Mallard
Summit Custom Homes, L.L.C.
120 S.E. 30th St
Lee's Summit, MO 64082

Re: 3119 S.E. 3rd Terrace – Roof Header Support
Lot 113
Lee's Summit, MO

Dear Mr. Mallard,

This letter is in regard to the support of the porch roof header for the above mentioned property. We understand that the header which frames into the corner of the house at the end of the front porch was extended into the exterior wall framing is supported by a cripple stud and a king stud.

Based on our evaluation of the framing condition, the cripple stud and king stud are adequate for the support of the header. No corrective measures are required.

We trust this report will meet your needs. If you need any additional information, please contact this office.

Sincerely,

VAN DEURZEN AND ASSOCIATES, P.A.

Chad M. Streeter, P.E.



10/5/2015