

PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20141075, Building Permit - Commercial
Address: 3321 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
In-wall Inspection	Mark Harding	Failed	Thursday, October 08, 2015

Corrective Action Required

1	Misc 1	-install protection plates and plates straps on plates bored at 50% 3rd failed, b,1,2,3 ok for prerock tub walls 4th no bsmt failed for prerock-1,2,3,4 ok,BSMT FAILED bsmt failed again
---	--------	--

All Rough Inspection - Commercial	Mark Harding	Not Ready	Thursday, October 08, 2015
--	--------------	-----------	----------------------------

Corrective Action Required

1	Misc 1	not ready bsmt , 1st floor, hvac sprinkler , firecaulking, plumbing plates, electrical panels.
---	--------	--

Comments: