

PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20150014, Building Permit - Commercial
Address: 508 NW MURRAY RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rough Electrical Inspection - Commercial	Mike Copeland	Partial	Tuesday, October 27, 2015

Partial Correction
1 Misc 1

FEEDER TERMINATIONS AT FLOOR DISTRIBUTION PANELS: NO ISSUES FOUND AT PANELS 1D, 2D;

Partial Correction
2 Misc 1

INSEPECTED AND APPROVED 3RD AND 4TH FLOOR MAIN DISTRUBUTION PANELS AND SUB-PANELS IN UNITS.

Rated Assembly Inspection	Mike Copeland	Partial	Tuesday, October 27, 2015
----------------------------------	---------------	---------	---------------------------

Partial Correction
1 Misc 1

1ST FLOOR:
OK TO TAPE, MUD & FIRE-STOP:
RATED CEILINGS AND WALLS AT ALL UNITS ELEVATOR MACHINE ROOM; E108; CORRIDOR CEILING AND WALLS; 119 EXCEPT SOUTH WALL; 120 EXCEPT NORTH WALL;

Partial Correction
2 Misc 1

2ND FLOOR: OK TO TAPE, MUD & FIRESTOP: CORRIDOR CEILING AND WALLS; RATED CEILINGS AND WALLS AT: ALL UNITS; 208; 219; 220;

Partial Correction
3 Misc 1

3RD FLOOR: OK TO TAPE, MUD & FIRE-STOP ONE LAYER 5/8" TYPE X GWB AT: CORRIDOR CEILING; ELECT & DATA RMS WALLS. WALLS AND CEILINGS AT UNITS 302*; 311; 312*; 313; 314; 315; 317; 318; 321; 323; 324; 327; 332; 333; CORRIDOR WALLS; 319; 320;

*EXCEPT ROOF DRAINS & STAIRWELL WALLS

Partial Correction 4 Misc 1	STAIRWELL WALLS NOT READY FOR INSPECTION 4TH FLOOR: OK TO TAPE, MUD & FIRE-STOP ONE LAYER 5/8" TYPE X GWB AT: UNITS 412; 413*; 414*; 423; 424; 427*; CORRIDOR WALLS ONLY ; E428; E429; 411; 419; 420; CORRIDOR CEILING
Partial Correction 5 Misc 1	
Corrective Action Required 6 Misc 1	OK TO TAPE, MUD AND FIRE-SEAL CEILINGS AND WALLS AT ELEVATOR LOBBIES AT: 4TH FLR; 3RD FLR; 2ND FLR;
Partial Correction 7 Misc 1	PROTECTION OF PENETRATIONS TO BE SPECIFIED BY A/E; RATED WALLS AT STAIRWELL SHAFTS: OK TO COVER WHEN READY 1" SHAFT LINER IN PLACE AT EAST & WEST STAIR TOWERS FROM 1ST FLR TO 4TH FLR ELEVATION.Y
Partial Correction 8	-WEST TOWER, FIRST LAYER APPROVED 1ST AND 2ND FLOOR. -EAST TOWER, FIRST LAYER APPROVED ALL FLOURS.

Comments: