

CODES ADMINISTRATION

Temporary Certificate of Occupancy

Permit #: PRCOM20150014

Address: 508 NW MURRAY RD, LEES SUMMIT, MO 64081

Inspected On: Friday, March 18, 2016

Inspected By: John Borns

Expiration Date: 5/26/2016 12:00:00 AM

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Occupancy Inspection - John Borns Temporary C of O Friday, March 18,

Codes Commercial

Corrective Action Required:

5 Misc 1 REMOVE FROM ROOFTOP ALL UNUSED MATERIALS AND DEBRIS.

SIZABLE SHEET METAL PARTS LEFT NEAR RTU'S. LEAVE NO SCREWS, NAILS, OR OTHER LOOSE MATERIAL ON ROOF

2016

MEMBRANE.

Corrective Action Required:

3 Misc 1 DEPARTMENTS APART FROM CODES:

WATER DEPARTMENT: APPROVED

FIRE DEPARTMENT: OK PER CPT WEISSENBACH PUBLIC WORKS: SIDEWALK APPROVAL PENDING

PLANNING: SEE SEPARATE REPORT

Corrective Action Required:

2 Misc 1 WHEN LANDSCAPING IS COMPLETED TRIM SANITARY PLUMBING

CLEANOUT RISERS TO NEAR GRADE.

Corrective Action Required:

1 Misc 1 UNTERMINATED ELECTRICAL CONDUCTORS PROTRUDING FROM

EXTERIOR WALLS. LUMINAIRES TO BE INSTALLED?