

FIRE DEPARTMENT

PLANS REVIEW CONDITIONS

Permit No: PRCOM20160560

Project Title: LEES SUMMIT NORTH HIGH

SCHOOL - INTERIOR

ALTERATIONS

Location:

901 NE DOUGLAS ST, LEES

SUMMIT, MO 64086

Type of Work:

Occupancy Group: E

Description: OFFICE RENOVATIONS
Construction Type: Type IIB (Unprotected)

Map Page:

Date: May 18, 2016

Applicant:

JAYHAWK FIRE SPRINKLER CO INC 12030 S. HEDGE LANE TERRACE

OLATHE, KANSAS 66061

Primary: (913) 422-3770

Listed below are requirements from our department for the project noted above. If you have any additional questions, please contact our department for further clarification.

Sprinkler Plan Review Reviewed By: Joe Dir Released for Construction

1. 2012 IFC 901.6- Inspection, testing and maintenance. Fire detection, alarm and extinguishing systems shall be maintained in an operative condition at all times, and shall be replaced or repaired where defective. Not required fire protection systems and equipment shall be inspected, tested and maintained or removed.

CURRENT FIRE SPRINKLER SYSTEM SHALL BE CURRENT WITH THE REQUIRED ANNUAL MAINTENANCE AND SERVICE WITH A CURRENT TAG ON THE RISER.

(VERIIFED AT INSPECTION)

The applicant understands that the requirements listed above must be corrected to conform to applicable City Codes and Ordinances.