LEE'S SUMMIT

CODES ADMINISTRATION

Temporary Certificate of Occupancy

Permit #:	PRCOM20150016
Address:	518 NW MURRAY RD, LEES SUMMIT, MO 64081
Inspected On:	Wednesday, June 15, 2016
Inspected By:	John Borns
Expiration Date:	6/30/2016 12:00:00 AM

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:		Inspector:	Outcome:	Date:		
Occupancy Inspection - Codes Commercial		John Borns	Temporary C of O	Wednesday, June 15, 2016		
Corrective Action Required:						
1	Misc 1	COMPLETE FINISH SITEWORK				
Corrective Action Required:						
2	Misc 1	RESOLVE ANY PLANNING ISSUES				
		RESOLVE ANY FIRE DEPT ISSUES				
		RESOLVE ANY WATER DEPT ISSUES				
		RESOLVE ANY PUBLIC V	NORKS DEPT ISSUES			
Corrective Action Required:						
3	Misc 1	ROOFTOP:				
		-HINGE KITS REQ'D ON	GREASE EF'S			
		-FINAL CLEAN ROOF SU	JRFACE OF UNUSED MA	TERIAL AND DEBRIS		
Corrective Action Required:						
5	Misc 1	COMPLIANT HANDRAILS REQUIRED AT EXTERIOR STAIR AT SW.				
		TEMPORARY PROVISOR	NS ARE ACCEPTABLE.			
Corrective Action Required:						

6 Misc 1 COMPLIANT GUARDS AND HANDRAILS REQUIRED AT INTERIOR STAIR SW AND RAMP SW. TEMPORARY PROVISONS ARE ACCEPTABLE.

Corrective Action Required:

7 Misc 1 BACKFLOW PROTECTION REQ'D AT ICEMAKER, COFFEE MAKERS, CARBONATED BEVERAGE FEED LINE, ETC -- TO BE VERIFIED

Corrective Action Required:

8 Misc 1 FIRESTOP HORIZONTAL CHASE AT ELEVATOR MACHINE ROOM Corrective Action Required:

9 Misc 1 SEAL ALL EXTERIOR WALL OPENINGS