

CODES ADMINISTRATION

Temporary Certificate of Occupancy

Permit #: PRCOM20150014

Address: 508 NW MURRAY RD, LEES SUMMIT, MO 64081

Inspected On: Friday, June 17, 2016

Inspected By: John BornsBob BurnsMitch Plemmons

Expiration Date: 7/7/2016 12:00:00 AM

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection: Inspector: Outcome: Date:

Occupancy Inspection - John Borns Temporary C of O Friday, June 17,

Codes Commercial 2016

Corrective Action Required:

1 Misc 1 REMOVE FROM ROOFTOP ALL UNUSED MATERIALS AND DEBRIS.

SIZABLE SHEET METAL PARTS LEFT NEAR RTU'S. LEAVE NO SCREWS,

NAILS, OR OTHER LOOSE MATERIAL ON ROOF MEMBRANE.

Corrective Action Required:

2 Misc 1 DEPARTMENTS APART FROM CODES:

WATER DEPARTMENT: APPROVED

FIRE DEPARTMENT: OK PER CPT WEISSENBACH PUBLIC WORKS: SIDEWALK APPROVAL PENDING

PLANNING: SEE SEPARATE REPORT

Corrective Action Required:

3 Misc 1 WHEN LANDSCAPING IS COMPLETED TRIM SANITARY PLUMBING

CLEANOUT RISERS TO NEAR GRADE.

PW-Sidewalk Inspection	Bob Burns	Passed	Friday, June 17, 2016
Occupancy Inspection - Public Works	Mitch Plemmons	Passed	Friday, June 17, 2016