

CODES ADMINISTRATION

Temporary Certificate of Occupancy

Permit #: PRCOM20150016

Address: 518 NW MURRAY RD, LEES SUMMIT, MO 64081

Inspected On: Monday, July 11, 2016

Inspected By: John Borns

Expiration Date: 7/28/2016 12:00:00 AM

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection: Outcome: Date:

Occupancy Inspection - John Borns Temporary C of O Monday, July 11,

Codes Commercial 2016

Corrective Action Required:

2 Misc 1 FIRESTOP HORIZONTAL CHASE AT ELEVATOR MACHINE ROOM

Corrective Action Required:

3 Misc 1 SEAL ALL EXTERIOR WALL OPENINGS

Corrective Action Required:

4 Misc 1 COMPLETE FINISH SITEWORK

Corrective Action Required:

5 Misc 1 RESOLVE ANY PLANNING ISSUES

RESOLVE ANY WATER DEPT ISSUES

RESOLVE ANY PUBLIC WORKS DEPT ISSUES

Corrective Action Required:

7 Misc 1 COMPLIANT HANDRAILS REQUIRED AT EXTERIOR STAIR AT SW.

TEMPORARY PROVISONS ARE ACCEPTABLE.

Corrective Action Required:

8 Misc 1 COMPLIANT GUARDS AND HANDRAILS REQUIRED AT INTERIOR

STAIR SW AND RAMP SW. TEMPORARY PROVISONS ARE ACCEPTABLE.

Corrective Action Required:

9 Misc 1

IMC 507.16 COMMERCIAL KITCHEN GREASE HOOD PERFORMANCE TEST: NEBB-CERTIFIED REPORT REQUIRED TO BE SUBMITTED TO INSPECTOR WHEN EQUIPMENT IS OPERATIONAL AND BEFORE COMMERCIAL USE. SMOKE CAPTURE TEST TO BE CERTIFIED BY 3RD PARTY OR WITNESSED BY INSPECTOR BEFORE ANY USE IS

APPROVED.