

FIRE DEPARTMENT

PLANS REVIEW CONDITIONS

Permit No: PRCOM20161245 Date: July 25, 2016

Project Title: HYVEE MARKET GRILL Applicant:

Location:

310 SW WARD RD, LEES SUMMIT, MO AMERICAN FIRE SPRINKLER CORPORATION

4081 PO BOX 958

Type of Work: MISSION, KS 66201

Occupancy Group: M

Description: INTERIOR ALTERATIONS TO

EXISTING GROCERY STORE -MODIFY CAFETERIA INTO RESTAURANT AND BUILD

MEDICAL CLINIC

Construction Type: Type IIIB (Unprotected)

Map Page:

Primary: (913) 722-6900

Listed below are requirements from our department for the project noted above. If you have any additional questions, please contact our department for further clarification.

Sprinkler Plan Review Reviewed By: Jim Eden Released for Construction

1. 2012 IFC 901.6- Inspection, testing and maintenance. Fire detection, alarm and extinguishing systems shall be maintained in an operative condition at all times, and shall be replaced or repaired where defective. Not required fire protection systems and equipment shall be inspected, tested and maintained or removed. THE EXSISTING FIRE SPRINKLER SYSTEM RISER SHALL BE CURRENT WITH THE REQUIRED ANNUAL MAINTENANACE/SERVICE WITH A CURRENT SERVICE TAG ON THE RISER. (verified at inspection)

The applicant understands that the requirements listed above must be corrected to conform to applicable City Codes and Ordinances.