

**PLANNING AND CODES ADMINISTRATION DEPARTMENT  
220 SE GREEN STREET  
LEE'S SUMMIT, MO 64063  
(816) 969-1200 FAX (816) 969-1201**

## Inspection Summary

---

Permit #:PRCOM20160277, Building Permit - Commercial  
Address: 1101 NW INNOVATION PKWY, LEES SUMMIT, MO 64086

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Underslab Plumbing Inspection - Commercial</b>	John Borns	Partial	Friday, July 29, 2016

Partial Correction

1	THE FOLLOWING AREAS ARE APPROVED	STORM SEWER AT THE FOLLOWING LOCATIONS: 12" STORM LINE AT 15 LINE SLOPING EAST BETWEEN O AND R TO 10.5 LINE; TRANSITION TO 8" LINE TO AA LINE; <b>8" PVC LINE FROM E.2/11.5 TO E.2/9.3; 10" PVC FROM E.2/9.3 TO K.2/9.3;</b>
---	----------------------------------	---

Partial Correction

2	THE FOLLOWING AREAS ARE APPROVED	SANITARY WASTE AND VENT 2 INCH TO 4 INCH AT W LINE TO 10 LINE WITH BATH GROUP; 6" PVC ON (K.8) FROM (11.6) TO (14) + FIVE BRANCHES; 4" PVC FROM T.5/9.2 TO T.5/5.6 TO N.2/5.6 TO N.2/4.2; <b>6" PVC ON (K.8) FROM (11.6) TO (11.2); 3" PVC ON (11.4) FROM (E.5) TO CONNECTION W/ 4" AT (K.8); 2" PVC BRANCH OFF 3" PVC @ (E.5);</b>
---	----------------------------------	--

Partial Correction

3	Misc 1	OK TO COVER WHEN READY UNDER-SLAB DRAIN LINES AT: AREA "A" COMPLETE; AREA "C" IN PROGRESS S OF (K);
---	--------	---

<b>Underslab Electrical Inspection - Commercial</b>	John Borns	Partial	Friday, July 29, 2016
---	------------	---------	-----------------------

Partial Correction

1	Misc 1	NO ISSUES FOUND ON UNDER-SLAB ELECTRICAL CONDUIT MATERIAL & WORKMANSHIP: THREE 4" PVC CONDUITS UNDER GRADE BEAM AT DD/13.2 TO 80' NORTH; THREE 4" + TWO 1-1/2" PVC CONDUITS EXTENDED N TO SERVER RM; SIX 3" + ONE 1-1/4"
---	--------	--

FROM SERVER RM SW TO ~T/11, THEN TWO 3" S TO Z/10.25;  
THREE 1-1/2" PVC FROM SERVER RM TO WALL PENETRATIONS AT  
K/13.5; TWO 2" PVC FROM WALL PENETRATIONS AT K/13.5 TO  
SW -- SWEEPING TO WEST N OF SERVER RM; ALL CONDUITS IN  
VICINITY OF M/13.5 IN PLACE AND INSPECTED INCLUDING  
CONNECTIONS AT WALL PENETRATIONS AT K/13.5 OK TO COVER  
WHEN READY; TWO 2" CONTINUING + SIX 4" & FOUR 3" PVC  
FROM SERVER RM WEST TO O.1/10.75, **THEN WEST BETWEEN (O)  
& (Q) TO (5.6); SIX 4" THEN CONTINUING WEST TO (3.5); TWO 3"  
STUBBED UP AT SPACE 2-153A; TWO 3" SWINGING NORTH AT  
(3.5); TWO 2" TO ABOVE GRADE AT Q/5;**

**Comments:**