

FIRE DEPARTMENT

PLANS REVIEW CONDITIONS

Permit No: PRCOM20161602

Project Title: ALLIED SERVICES

Location:

2706 NE INDEPENDENCE AVE, LEES

SUMMIT, MO 64064

Type of Work:

Occupancy Group: B

Description: TENANT BUILD OUT FOR

OFFICE SPACE

*underslab plumbing permit PRCOM20161638 Construction Type: Type IIB (Unprotected)

Map Page: 175R

Date: August 16, 2016

Applicant:

ADVANTAGE FIRE PROTECTION SYSTEMS INC

404 B NW 11TH ST

BLUE SPRINGS, MO 64015

Primary: (816) 224-3400

Listed below are requirements from our department for the project noted above. If you have any additional questions, please contact our department for further clarification.

Sprinkler Plan Review Reviewed By: Joe Dir Released for Construction

1. 2012 IFC 901.6- Inspection, testing and maintenance. Fire detection, alarm and extinguishing systems shall be maintained in an operative condition at all times, and shall be replaced or repaired where defective. Not required fire protection systems and equipment shall be inspected, tested and maintained or removed. THE EXISTING FIRE SPRINKLER SYSTEM SHALL BE CURRENT WITH ALL REQUIRED SERVICE MAINTENANCE FOR THE FIRE SPRINKLER SYSTEM. A CURRENT SERVICE TAG SHALL BE POSTED ON THE SPRINKLER RISER. (VERIFIED AT INSPECTION)

The applicant understands that the requirements listed above must be corrected to conform to applicable City Codes and Ordinances.