PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20152438, Building Permit - Commercial Address: 3381 NW CHIPMAN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

In-wall Inspection John Borns Partial Friday, January 06, 2017

Partial Correction

1 Misc 1 OK TO COVER WHEN READY LIGHT-GAUGE STEEL WALL FRAMING

+ IN-WALL SYSTEMS AT FOLLOWING LOCATIONS:

ONE-SIDING OF ELECT[115]; VEST [118] N WALL TWO LAYERS S FACE; TWO 4' WIDE STACKS @ PLATFORM [117] FOR DUCTWORK; MECH [145]; WOMENS RR [103]; MEN'S RR[104]; JANITOR [105]; FAMILY RR [106]; ELECT [115] SOUTH WALL SOUTH FACE; 102;

129; 144; **114 NORTH WALL**;

SOUTH WALL OF E-W LEG OF N END OF CORR [128]; [131]-[143];

[145]; [147]-[150]; [157]; [151] THROUGH [156];

IN-WALL OK FOR: SANCTUARY 113 STARTING FROM PLATFORM (117) STAIR ALL THE WAY AROUND TO THE OTHER SIDE; RM 107

TO 112; DOUBLE STUD WALL BETWEEN 113&102

Rough Framing John Borns Not Ready Friday, January 06, 2017 **Inspection -**

Commercial

Partial Correction

1 Misc 1 OK TO COVER WHEN READY L.G. STEEL FURRING FRAMING PER

WALL SECTION 1/E1 ON ERECTION DRWG. TAPCON FASTENING

APPROVED PER DETAIL 4/S4.01.

-RAISED FLOOR FRAMING UNDER RM 121-127; SAME AT 120;

Partial Correction

2 Misc 1 SOUTH WALL OF 120 OK FOR CONSTRUCTION OF ADJACENT

RAMP;

Corrective Action Required

3 Misc 1

FRAMING OF PLATFORM AT [128] COVERED AT BOTTOM WITH INSULATION -- NOT APPROVED

Comments: