PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20162583, Building Permit - Commercial Address: 20 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:	
	·			
In-wall Inspection	John Borns	Partial	Thursday, January 19, 2017	
Partial Correction 1 Misc 1		OK TO COVER WHEN READY LIGHT-GAUGE STEEL WALL FRAMING + IN-WALL SYSTEMS AT FOLLOWING LOCATIONS: 1C122 SOUTH WALL; 1C216; 1C217; CUT-IN DOOR 1C219; 1D23 NW WALL B/F; 1D25; 1D26; IN-FILL AT 1D22 N WALL B/F; 1D24 B/F; 1D25 O/SF; 1D26 W WALL B/F; 1D221 E WALL B/F; 1C223; 1C221 CONTINGENT ON SEGMENT OF CORRIDOR SMOKE WALL BEING		
		WALLS; [1C118] E & NW; [1C120] 2 BOCA PLATES IN PLACE; [XXX] F DOOR (1D23); [1C118] W WALL; WALL; CHASE AT [218] SE CORNE	MOKE-SEALED; C137; E/NE WALL; 1C120 & 121 B/F; 1C218 E & S ALLS; [1C118] E & NW; [1C120] S WALL; [1C218] N WALL AFTER BOCA PLATES IN PLACE; [XXX] PER RFI; WALL AT/ADJACENT TO DOR (1D23); [1C118] W WALL; [1C118A] E WALL; [1C119] S ALL; CHASE AT [218] SE CORNER; [1C219] E & W WALLS; WING ALL @ [1C219] S; N WALL OF NEWLY-ENCLOSED CLOSET PER #5 AT [1D23] SOUTH;	
		B/F = BOTH FACES O/SF = OUTSIDE FACE		
Rated Assembly Inspection	John Borns	Partial	Thursday, January 19, 2017	
Partial Correction 1 Misc 1		GWB AT 1 HR FIRE-RATED WALLS: OK TO TAPE, MUD, & FIRE-SEAL WHEN READY 5/8" TYPE X GWB INSTALLATION @ FOLLOWING LOCATIONS: 1D25 & 1D26 WEST WALL; 1C133 S WALL B/F; 1D25 & 1D26 BACK FACES, CONTINGENT ON APPROVABLE FIRE-STOPPING TO BE INSPECTED WHEN READY; N&W WALLS OF 1D24 UP TO 10' AFF B/F; LINER BOARD HIGH ON WALL @ 1D24		

NE B/F; 1D24 NE; [1D23] W WALL N + S WALL W;

B/F = BOTH FACES

Comments: