# PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

## **Inspection Summary**

Permit #:PRRES20162559, Building Permit - Residential Address: 1344 NE BRANDYWINE RD, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date: **Electrical Service** Khanh Nguyen Tuesday, January 31, 2017 Passed **Inspection - Residential Gas Service Inspection** - Khanh Nguyen Passed Tuesday, January 31, 2017 Residential All Rough Inspection -Khanh Nguyen Failed Tuesday, January 31, 2017 Residential

Corrective Action Required

1 Misc 1 FRAMING:

-GARAGE PORTAL BRACE WALLS-NAIL THE SHEATHING TO DOUBLE STUDS ON EACH SIDE OF WALL WITH 8D@3' OC

-ANCHOR GARAGE AND BASEMENT SILL PLATE PER CODE. MAKE

SURE TO HAVE MIN. 2 ANCHORS FOR EACH SHORT PLATE

-SUPPORT HIPS ABOVE GARAGE

-NAIL THE CORNER STUDS AT BED/GARAGE WALL INTERSECTION

-HAVE ENGINEER OK THE SPLICED RAFTERS ABOVE

GARAGE/FOYER

-INSTALL HANGERS FOR CEILING JOIST-LVL CONNECTIONS ABOVE

**KITCHEN** 

-DECK DOOR-INSTALL SECURITY BLOCKING PER LS SECURITY

CODE

-BRACE THE 18" LVL BEAM ENDS FROM ROTATION

-SUPPORT THE LVL HIP TO MASTER BED CEILING BEAM

-THE HALLWAY WALL OUTSIDE MASTER BED AND SUNROOM

WALL ARE NOT BEARING WALLS

- -PROVIDE SOLIDBLOCKING UNDER 18" LVL POINT LOAD (BELOW MUD SINK)
- -TOE NAIL ALL JOISTS TO TOP PLATES AND SILL WITH 3-8D NAILS
- -EXPOSE DECK FIREPLACE SPACE
- -3 STUD SUPPORT FOR LVL AT MASTER CLOSET

### PLUMBING:

-PROTECT PVC AT BASEMENT BATH UNDER STAIR

#### ELECTRICAL:

- -BOND THE HYDROTUB MOTOR TO THE METAL VALVE ASSY
- -MAKE SURE TO PROVIDE ACCESS TO UFER AT FINAL.

#### MECHANICAL:

- -PROVIDE MIN 1" CLEARANCE AROUND B-VENT IN CHASE
- -PROVIDE COMBUSTION AIR OPENINGS PER CODE FOR MECH.

#### RM

-VENT BASEMENT BATH FAN

\*\*DO NOT INSULATE

**Comments:**