PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20161179, Building Permit - Commercial Address: 1820 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Gas Piping Inspection - John Borns Partial Tuesday, March 14, 2017

Commercial

Partial Correction

1 Misc 1 GAS FEEDER LINE TRENCHED, LAID, AND BACKFILLED FROM

PRINT MARK (G1) TO (G2); COMPLETE EAST TO BLDG ENTRY AT NE CORNER. INFRASOURCE PRESSURE TEST WITNESSED AT 100 PSI STEADY FOR >10 MINUTES. FEEDER PIPING TO BUILDING OK

FOR USE.

TRACER WIRE IN PLACE

Partial Correction

2 Misc 1 GAS PIPING FROM BUILDING ENTRY TO WATER HEATER

LOCATION ON 2ND FLOOR:

NO ISSUES ON VISUAL INSPECTION.

PRESSURE TEST HELD STEADY AT >= 10 PSI FOR >=10 MIN. OK

FOR USE WHEN READY.

Rated Assembly John Borns Partial Tuesday, March 14, 2017

Inspection

Partial Correction

1 Misc 1 RATED WEST AND EAST STAIRWELLS: OK TO TAPE, MUD AND

FIRE-STOP UNIT FACE AND STAIRWELL FACE FULL HEIGHT BOTH

STAIRS

Partial Correction

2 Misc 1 OK TO TAPE, MUD AND FIRE-STOP WHEN READY 5/8" TYPE X

GWB AT 1ST FLOOR CEILINGS AND WALLS AT: 106; 108; 113; 114; 115; 109; 111 INCLUDING EAST WALL ABOVE CEILING; MAIN

CORRIDOR; 102-4 116-7

Partial Correction 3 Misc 1

OK TO TAPE, MUD AND FIRE-STOP WHEN READY 5/8" TYPE X GWB AT 2ND FLOOR CEILINGS AND WALLS AT: CORRIDOR; 206; 208; 213; 214; 215; 209; 211; 202-4 216-7

Partial Correction 4 Misc 1

Comments:

OK TO TAPE, MUD AND FIRE-STOP WHEN READY 5/8" TYPE X GWB AT 3RD FLOOR CEILINGS AND WALLS AT: CORRIDOR; 306; 308; 309; 311; 313; 314; 315; 302-4 316-7