PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20161426, Building Permit - Commercial Address: 720 NW BLUE PKWY, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Commercial	John Borns	Partial	Wednesday, March 15, 2017
Corrective Action Require	ed		
1 Misc 1		ONE ELECT RECEPT AT NE CORNER NEEDS SPARK ARRESTOR	
Corrective Action Require	ed		
2 Misc 1		MC CABLE RUN FOR TV AT P.O.S REPLACED.	. NW IS DAMAGED; NEEDS TO BE
Corrective Action Require	ed		
3 Misc 1		SWITCHES AT MDP TO BE LABELED.	
Corrective Action Required			
4 Misc 1		ROOFTOP:	
		- ELECTRICAL WIRING NOT TO BE ATTACHED TO GAS PIPE	
		- GAS PIPING TO BE SUPPORTED SOLID WITH SPACING PER IFGC.	
		SUPPORT AT BENDS AND TEES	
		 GAS PIPE SUPPORTS MUST BE CONSTRAINED FROM IDSPLACEMENT PROVIDE MANUFACTURER LITERATURE / INSTRUCTIONS FOR PIPE SUPPORTS IF NOT TO BE CLAMPED 	
		- REMOVE ALL DEBRIS & UNUSEI	D MATERIALS FROM ROOFTOP
		- GAS PIPE NOT PAINTED AT RTU	I'S
		- ELECT RECEPTS AT RTU'S NOT H	IOT FOR TEST
Corrective Action Require	ed		
5 Misc 1		RESOLVE ANY PLANNING ISSUES	(SUPERIOR-BOWEN)
Corrective Action Require	ed		
6 Misc 1		RESOLVE ANY FIRE DEPT ISSUES	
Corrective Action Require	ed		
7 Misc 1		RESOLVE ANY WATER DEPT ISSU	ES
Corrective Action Required			
8 Misc 1		OCCUPANCY STATUS: OK TO SE TRAINING, FIXTURING, STOCKIN	-

PRIOR TO APPROVAL.

Comments: