

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRPWLD20161487, Public Works Land Disturbance Permit
RESOURCE RECOVERY PARK - COMPOST PAD CONSTRUCTION
Address: 2101 SE HAMBLER RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
PW-ESC - (Vegetation/Ground Cover)	Brice Lawson	Partial	Friday, March 24, 2017

Corrective Action Required

- 2 Brice Lawson 03/17/2017 2:48 PM
The berms surrounding the detention basin and the compost pad are partially vegetated. The outer east slope of the detention basin has a good amount of vegetation on it.

Establish proper vegetation on the slopes.

Informational

- 1 Brice Lawson 10/31/2016 6:49 AM
The slopes around the detention basin have been hydroseeded with fescue and 12-12-12 fertilizer. It appeared that the ground was loose and that there is a good amount of hydroseed sprayed on these areas.

Corrective Action Required

- 3 Brice Lawson 03/24/2017 11:24 AM
Establish proper vegetation on the slopes of the berms surrounding the detention basin and compost pad.

Establish proper vegetation in the bottom of the detention basin. There is a large amount of water that is holding in the detention basin.

I met with Rick Crider to go over these issues. He plans figure out why the detention basin is not draining and to spread compost, seed and hydro mulch in the bottom of the detention basin and on the slopes of the berms surrounding the detention basin and compost pad. I informed him that this permit is valid until June and that extension can be granted upon written request.

Comments:
